

Pitco
P.O. Box 501
Concord, NH 03301
Tel 603-225-6684
Fax 603-225-8497



Applies To:

See List Below

Subject:

PARTS BULLETIN

Robertshaw Gas Valves

Date: 10/19/04

Bulletin #: P278

Gas Valve Voluntary Safety Recall

This bulletin is in response to the attached memo from Invensys regarding the Robertshaw series 7000 gas valve, to inform you that our Solstice Fryers are NOT effected, with the exception of the SG CE millivolt fryer.

There are a number of older model units that are effected and we are asking that all part numbers listed below be quarantined. We will be contacting you shortly to provide details on how to proceed.

If you have any situations that require an immediate replacement of this valve at a customer's facility, please contact Pitco on how to proceed.

We realize that there may be many questions as this issue has affected other manufacturers using similar Invensys components. As soon as any further information is available, we will promptly notify you and post the information on our web site at www.pitco.com/RS7000.htm

The part numbers affected are:

60132902
B8002701
B8002702
P5045638
P5045639
P5045642
P5045644
P5045650
P5045652
P5045658
P5045659
PP10777
PP10955
PP10956
PP11110
PP11112