



## **PARTS BULLETIN**

### **Robertshaw Gas Valves**

Date: 10/21/04


Bulletin #: P279

### **Identifying A Reworked Valve**

This bulletin is to help identify valves that have been reworked by Robertshaw to address the valve recall identified in bulletin P278. Robertshaw has been reworking valves in two modes by replacing the magnet in the factory, or replacing the magnet in a piece of equipment that has already been in use in the field.

If Robertshaw has reworked the valve in the factory, the valve will be marked with a green stripe on the inlet side of the valve body, and may also have a green stripe on the magnet as well as a black circle with a letter in the center, stamped on the body.

If Robertshaw reworks the valve in the field, the magnet will have a green strip on it.



**OR**



In either case, if the valve has been identified as reworked by Robertshaw, it is no longer included in the 7000 series recall, regardless of the date code on the valve body.

As soon as any further information is available, we will promptly notify you and post the information on our web site at [www.pitco.com/RS7000.htm](http://www.pitco.com/RS7000.htm)

The part numbers affected are: 60132902, B8002701, B8002702, P5045638, P5045639, P5045642, P5045644, P5045650, P5045652, P5045658, P5045659, PP10777, PP10955, PP10956, PP11110, PP11112